

Over time, certain kinds of acrylic can show fine lines, often referred to a minor surface “crazing” or “checking” that can resemble spider webs.

These surface blemishes are cosmetic flaws and are not harmful to the integrity of your spa shell.

It can, however, be repaired and restored to its original luster.

You will need a heat gun to perform this procedure.



Before you begin you will need to drain the spa. Do not use electrical appliances around a filled spa!



Turn on the heat gun and apply high heat 5” to 10” from the surface.

Do not keep the heat in one place for longer than *five seconds at a time*. **Do not allow the surface to scorch.**



When the acrylic has cooled (wait about 30 minutes), buff out the surface with a soft cloth. Do not touch the surface when it is hot.